



66/ ST Found ST switch found but not expected

Start

Repair or replace

One or more spotting tongs are broken or binding

Click here to email KMK experts

Clean, and reset tension

Spotting tong clutch slipping

Spotting tong solenoid not energizing

Check fuses on CPU board

Check spotting tong drive adjustment

Square shaft drive gear out of adjustment

ST switch bad or bad wiring

Repair or replace