



Gearbox Clutch  
Disengages at 180  
When Deck is Full

Start

Adjust as needed



180 degree  
turret interlock is  
adjusted to low

Yes

No

Latch that  
holds long link  
rearward is  
functioning  
properly

No

Inspect and adjust as  
needed

Yes

Click to Email KMK  
Experts