
Rake raises but does not stay up.
Rake trip mechanism fully engaged
NO
Check rakeboard height adjustment and correct as needed.
YES
Pit cushion trigger link out of adjustment
YES
Perform adjustment to cushion trigger linkage
NO
Bind in pit cushion linkage
YES
Correct as required
NO
Ball stuck under pit cushion
NO
Click to email KMK Expert
YES
Check all area that move pins for a malfunction (Pit Conveyor, Pin Elevator, Turnaround Pan, Cross Conveyor, Pin Gate, etc)