



**KEGEL
MECHANICS
KLUB**

65/ "G" Found

Start

Check for broken parts, missing springs and solenoid plunger stuck

Yes

Problem with sweep release

No

Align assembly to engage pin on sweep wagon

Yes

Sweep release assembly not aligned

No

Replace switch and inspect wiring between switch and the Nexgen box

yes

"G" switch problem

No

Click here to email KMK experts

No

Was sweep motor replaced

Yes

Insure the correct rotation of the motor

Yes

Sweep wagon all the way forward

No

Check sweep arms and sweep crank links