



**KEGEL
MECHANICS
KLUB**

Buffer Brush Goes
Up/Down Continuously

Start

Tighten Set Screw on
Flat Spot of Brush Lift
Motor

Brush Lift Cam Tight
on Motor Shaft



Yes

Adjust Micro Switch
Roller to Cam with .015
Gap



Micro Switch
Adjusted Properly



Yes

Click to Email KMK
Expert

Micro Switches
are Activating 0ch4 &
0ch5



No

Replace Broken Wire or
Reattach Loose Wire

Yes

GN/WH Wire
to 0ch4 or VT/YE to
0ch5 is Broken or
Loose



No

Replace Switch
P/N
153-1203