



Incorrect Score

Replace

Broken Pin
Detector Plate

Remove Pinholder,
Repair as Needed

Pin Detect Switch

Detection
Height is not
Correct

Adjust Stroke Limiter

Switch
Cluster Cam out of
adjustment

Adjust Switch Cluster
Cam

Click Here to Email
KMK Experts