



Pinsetter Fails to Cycle

Check adjustment for rake

Rake trip mechanism not working

Click here to email KMK Experts

Adjust as needed

Pit cushion lift rod out of adjustment

Bind in gearbox triggering

Inspect triggering to locate bind. Inspect for loose or broken parts and replace if needed. Lubricate and adjust as needed

Adjust as needed

Cushion trigger link gap is too wide

Trigger switch is out of adjustment

Adjust as needed

