



Pinsetter Uses Time
Delay on Second Ball

Start

Adjust as needed



1st and 2nd
ball light adjusted
properly

No

Yes

Time
delay module
functioning
properly

No

Correct or replace
module

Yes

Click to Email KMK
Experts